



PEZULA NATURE HOTEL & SPA



AGM – Facilities Summary Report -
September 2021

- Garden & Grounds
- Nursery
- Pathways and Lighting
- Bulk Infrastructure
- Ponds & Water Features
- Parking
- Suite Exterior Maintenance
- Suite Interior Infrastructure
- Ventilation and Baboon Project

Garden & Grounds

Clearing Old Undergrowth – Various Areas , Hotel Entrance , Suites 22 , 44 , 70 - Open Up Views

Before



After



Before



After





Garden & Grounds

No Dig Technique –

Creating new garden beds for
Nursery mother stock on grass
area suite 33-44





Garden & Grounds

Extending Pathways –

Creating additional pathways
In
garden area for leisure
walking





Garden & Grounds

Jungle Gym's - Construct 3 Jungle Gyms ,

Bridges over Water features





Nursery

Irrigation Project –
Numbering , Testing and
Mapping Irrigation Points
100+
mapped





Nursery

Greywater - Storage point
created at Nursery ,
connecting to Nursery irrigation
planned





Nursery

Plant Sales (Mini Stand at Deli
,
Estate Developers, Pezula
Estate





Nursery

Bokashi Composting -

Kitchen wet waste used for
Composting used in Nursery
propagation and Gardens





Pathways and Lighting :


Pathway Lighting - Maintained
at Moment





Bulk Infrastructure:

Sewerage System - Roots ongoing maintenance required- part of standing maintenance program





Ponds & Water Features

Greywater Catchpit - Catch Pit
created to continuously feed ponds





Ponds & Water Features

Pond Edges - Back fill with soil and
planting edges, main pond, koi
pond





Ponds & Water Features

Water Feature Maintenance –
Roots
removed from main system feeding
Suite 23





Ponds & Water Features

Pond Pumps - Timers Installed





Parking

Addition Parking Bays created

Special Purpose and Disabled Parking





Suite Exterior Maintenance

Roofs - Replace Roof slates ,
Baboon

damage , Repairing leaks

waterproofing





Suite Exterior Maintenance

Landing Decks - Replace rotten supports and decking as required





Suite Interior Infrastructure

Pitted Pipes





Suite Interior Infrastructure

Stopcock Corrosion Failure Leading
to
Water Damage





Ventilation and Baboon Project

Bedside Windows - Clear Bars





Ventilation and Baboon Project

Sliding Door Signage – Signage
Garden





Thank You

